



Used for fitting onto machine spindle for holding HSK tools.

Design

The adjusting screw on the machine spindle can be accurately adjusted to concentricity. Precise adjustment in face run-out with adjusting screws on mounting flange.

Includes

Clamping cartridge, cover ring, holding screw, and clamping screw.

Available for HSK-C 32, 40, 50, 63, 80, 100