



Used for fitting onto machine spindle or in standard SK adapters for holding HSK tools.

Design

The adjusting screw on the machine spindle can be accurately adjusted to concentricity.

Includes

Clamping cartridge, cover ring, and holding screw.

Available for HSK-C 32, 40, 50, 63, 80, 100